



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERTL. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:					
Company	David Shaver Manager	_			
OGM Steve Demczak Environmental Scientist II					

Inspection Report

Permit Number:	C0070041			
Inspection Type:	PARTIAL			
Inspection Date:	Wednesday, January 20, 2010			
Start Date/Time:	1/20/2010 10:00:00 AM			
End Date/Time:	1/20/2010 12:00:00 PM			
Last Inspection:	Friday, January 08, 2010			

Inspector: Steve Demczak, Environmental Scientist III

Weather: Temperature 30's, Snow Covered 16 inches

InspectionID Report Number: 2251

Reprocessing

Date

Accepted by: jhelfric 2/1/2010

Permitee: WEST RIDGE RESOURCES Operator: WEST RIDGE RESOURCES

Site: WEST RIDGE MINE

Address: PO BOX 1077, PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

	Total Permitted		
30.39	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

Other

Types of Operations ✓ Federal ✓ Underground State Surface County Loadout Fee Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee continues to meet this Special Condition of the current State of Utah permit to send water data electronically.

No violations were written.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Monday, January 25, 2010

Permit Number: C0070041 Inspection Type: PARTIAL

Inspection Date: Wednesday, January 20, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		V	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	V			
4.e	Hydrologic Balance: Effluent Limitations	✓			
5.	Explosives	V			
6.	Disposal of Excess Spoil, Fills, Benches	V			
7.	Coal Mine Waste, Refuse Piles, Impoundments	V			
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070041 Inspection Type: PARTIAL

Inspection Date: Wednesday, January 20, 2010

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

There is no permitting action with the Division.

2. Signs and Markers

The identification sign is after the main gate to the property. All information complied with the R645 Coal Rules.

4.a Hydrologic Balance: Diversions

The diversion were snow covered.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment pond did contained water but was not discharging during the inspection. No hazardous conditions were noticed during the inspection.

8. Noncoal Waste

The mine site was clear of non-coal waste materials.